ಕರ್ನಾಟಕ ಲೋಕಾಯುಕ್ತ

ನಂ:ಕಂ.ಲೋಕ್.ಬಿಸಿಡಿ 2518/2018

ಬಹುಮಹಡಿ ಕಟ್ಟಡ, ಬೆಂಗಳೂರು,ದಿನಾಂಕ:07/06/2018

ನೊಟೀಸು

ವಿಷಯ: ಹೆಚ್.ಎಸ್.ದೊರೈಸ್ವಾಮಿ ಎಂಬುವವರು ನಮ್ಮ ಸಂಸ್ಥೆಯಲ್ಲಿ ನೀಡಿರುವ ದೂರಿನ ಕುರಿತು.

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂದಪಟ್ಟಂತೆ ತಮಗೆ ಈ ಮೂಲಕ ಗೌರವಾನ್ವಿತ ಲೋಕಾಯುಕ್ತರವರ ಆದೇಶದಂತೆ ತಮಗೆ ಈ ಮೂಲಕ ತಿಳಿಯ ಪಡಿಸುವುದೆನೆಂದರೆ, ಗೌರವಾನ್ವಿತ ಲೋಕಾಯುಕ್ತರವರು ಚೌಡನಪಾಳ್ಯ ಕೆರೆಗೆ ಸಂಬಂದಪಟ್ಟಂತೆ ದಿನಾಂಕ: 03-07-2019 ರಂದು ಹೊರಡಿಸಿರುವ ಆದೇಶವನ್ನು ಇದರೊಂದಿಗೆ ಲಗತ್ತಿಸಿ ಕಳುಹಿಸಿದ್ದು, ಆದೇಶದಲ್ಲಿ ತಿಳಿಸಿರುವಂತೆ ಪ್ರಸ್ತುತ ವರದಿಯನ್ನು ದಿನಾಂಕ:06.11.2019 ರೊಳಗಾಗಿ ಸಲ್ಲಿಸತಕ್ಕದ್ದು.

ಮತ್ತು ದಿನಾಂಕ:06-11-2019 ರಂದು 3-00 ಗಂಟೆಗೆ ಖುದ್ದು ಗೌರವಾನ್ವಿತ ಲೋಕಾಯುಕ್ತರವರ ಮುಂದೆ ಹಾಜರಾಗತಕ್ಕದ್ದು.

ಗೌರವಾನ್ವಿತ ಲೋಕಾಯುಕ್ತರವರ ಆದೇಶದನ್ವಯ

ಅಪರ ನಿಭಂದಕರು ವಿಚಾರಣೆಗಳು-1

ಕರ್ನಾಟಕ ಲೋಕಾಯುಕ್ತ,ಬೆಂಗಳೂರು

- 1) The C.E.O., Namma Bangalore foundation, 2nd floor, No54, Rockline centre, Richmond Road, Bangalore.
- 2) The Tahsildar, Bangalore South Taluk, Bangalore
- 34) The A.D.L.R. Bangalore South Taluk, Bangalore
- ዓመ) Smt. Divyashree.V.G.Assistant Executive Engineer, BWSSB, Cauvery Bhavan, Bangalore
- S®) The Deputy Commissioner, Bangalore Urban District, Bangalore
 - (7) Sri. Bhupradha, Assistant Executive Engineer(Lakes), BBMP Head Office, Bangalore.

KARNATAKA LOKAYUKTA, BENGALURU

No:Compt/LOK/BCD-2518/2018 Date: 03-07-2019

ORDER

On behalf of the complainant no one is preset.

- 2. No one is present on behalf of the Bruhath Bengaluru Mahanagara Palike, Bengaluru.
- 3. On behalf of Karnataka State Pollution Control Board, Bengaluru, Sri Bhat, Law Officer, Sri D.R. Kumaraswamy, Senior Environmental Officer and Dr. Niranjan are present. They have submitted a status report dated 01-07-2019 along with certain photographs. It is useful to extract the said status report, which reads as hereunder:

"No. KSPCB/RO:BCS/EO/2019-20/

Date: 01-07-2019

INSPECTION REPORT OF SRI. M.C. RAMESH, KSPCB, REGIONAL OFFICE, BENGALURU CITY SOUTH

1	Lake Inspected	Gowdanapalya Lake, Bengaluru
2	Date of inspection.	29.6.2019.
 3	Persons Contacted	Sri. Lokesh-nearby resident Sri. Nagesh- nearby resident
4	Total Extent of the Tank	3 Acres 30 Guntas

MM

This lake is belongs to Karnataka Forest Department. It is bounded by residential area in all directions. The whole lake is filled up with Aquatic Plants. No industrial establishments are there in the nearby vicinity of the tank. Untreated sewage generated from Kumaraswamy layout was joining the tank in the North-Eastern direction through a storm water drain. A letter has been addressed to the Chief Engineer BWSSB by the Board by this office take immediate action to divert the sewage into the nearby STP. Photographs taken during inspection are enclosed with this report for kind perusal.²⁹

4. On behalf of BWSSB Smt Divyashree V.G, Assistant Executive Engineer is present. She has submitted a status report dated 02-07-2019. It is useful to extract the said status report, which reads as hereunder:

"ಖಷಯ:- ಗೌಡನ ಪಾಕ್ಯ ಕೆರೆಗೆ ಒಳಚರಂಡಿ ನೀರು ಹಲದು ಬರುತ್ತಿರುವ ಬಗ್ಗೆ ಕ್ರಮ ಕೈಗೊಂಡಿರುವ ವರಐ. ಉಲ್ಲೇಖ:- 1. ಸಂಖ್ಯೆ: ಬೆಂಜಮಂ/ಮುಅ(ನಿ)/ಅಮುಅ(ನಿ)-3/9006/ 2018-19 ಬಿ: 08.03.2019. 2. ಸಂ.ಬೆಂಜಮಂ/ಸ.ಕಾ.ನಿ.ಅ(ದ)-1/ಕಂ.ವ್ಯ/2337/2018-19 ಬ: 07.03.2019.

3. ಸಂ.ಬೆಂಜಮಂ/ ಸ.ಕಾ.ನಿ.ಉ(ದ)-1/ಸ.ಉ/335/2019-20 ಟ: 24.05.2019.

ಮೇಲ್ಕಂಡ ೩ಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಗೌಡನಪಾಕ್ಯ ಕೆರೆಗೆ ಹಲದುಬರುತ್ತಿರುವ ಒಕಚರಂಡಿ ೩೯ರನ್ನು ತಡೆಯಲು ಬೆಂಗಕೂರು ಜಲ ಮಂಡಆಯ ತ್ಯಾಜ್ಯ ೩೯ರು ೩ವ೯ಹಣಾ ೩ಭಾಗದ ವತಿಂಬಂದ ಎರಡು ಪ್ರತ್ಯೇಕ ಕಾಮರಾಲಗಳ ಪ್ರಸ್ತಾವನೆ ಇರುವುದರ ಬಗ್ಗೆ ಈ ಹಿಂಟನ ಪತ್ರ ಉಲ್ಲೇಖ ಸಂ.ಬೆಂಜಮಂ/ಸ.ಕಾ.೩೨೯(ದ)-1/ಕಂ.ವ್ಯ/2337/2018-19 ಬಿ: 07.03.2019 ರಲ್ಲ ತಮ್ಮ ಗಮನಕ್ಕೆ ಈಗಾಗಲೇ ತರಲಾಗಿರುತ್ತದೆ.

ಮುಂದುವರೆದಂತೆ ಪ್ರತ್ಯೇಕವಾದ ಎರಡು ಕಾಮರಾಲಗಳಾದ Work of P & L of 450mm dia NP-3 class RCC interceptor sewer to intercept sewage from the SWD from Mahaveer Gardenia Apartment to Srinivasa Theatre road,. Gowdanapalya. ಮತ್ತು Work of P & L of 450mm dia

m

NP-3 class RCC interceptor sewer to intercept sewage from the SWD from 3rd cross Minajnagar to Mahaveer Gardenia Apartment, Gowdanapalya ರ ಬೆಂಡರ್ ಪ್ರಕ್ರಿಯೆಯು ಈರಾರಲೇ ಆರಂಭರೊಂಡಿದ್ದು ಬೆಂಡರ್ ಬಯಸಿರುವ ರುತ್ತಿರೆದಾರರ ಚೆಸ್ಟಿಕಲ್ ಇಡ್ ಅನ್ನು ತೆರೆದು ಉತ್ತೀರ್ಣರೊಂಡ ರುತ್ತಿರೆದಾರರ ಫೈನಾಸ್ಸಿಯಲ್ ಇಡ್ ತೆರೆದು L1 ರುತ್ತಿರೆದಾರರ ಅನುಮೋದನೆರಾಲ ಕೇಂದ್ರ ಕಛೇಲಯಲ್ಲ ಪ್ರಕ್ರಿಯೆ ನಡೆಬರುತ್ತದೆಯೆಂದು ತಿಆರು ಬಂಬರುತ್ತದೆ. ತದನಂತರ L1 ರುತ್ತಿರೆದಾರಲರ ಕಾರ್ಯಾದೇಶ ಸಾಡುವ ಪ್ರಕ್ರಿಯೆಯನ್ನೊಳರೊಂಡಂತೆ ಸಕ್ರಮ ಪೂರ್ಣಕಾರಬಂದ ಮುಂಬನ ಕ್ರಮಕೈಗೊಳ್ಳಲಾರುವುದು.

ಮೇಲೆ ಸೂಜಿಸಿರುವ ಕಾಮಗಾಲಗಳನ್ನು ಕೈಗೊಂಡಲ್ಲ ಕುಮಾರಸ್ವಾಖ ಬಡಾವಣೆ, ಬನಶಂಕಲ ದೇವಸ್ಥಾನದ ಸುತ್ತಮುತ್ತಅನ ಕೊಳಚೆ ಪ್ರದೇಶಗಳಾದ ಸರಬಂಡೇಪಾಳ್ಯ, ಖುನಾಜ್ ನಗರ, ಉಮರ್ಬಾಗ್ ಬಡಾವಣೆ ಹಾಗೂ ಜಿ.ಹೆಚ್.ಜಿ.ಸಿ.ಎಸ್ ಬಡಾವಣೆ ,ಗೌಡನಪಾಳ್ಯ ಕೊಳಚೆ ಪ್ರದೇಶ ಮತ್ತು ಇತರೆ ಬಡಾವಣೆಗಳಾದ ಹಲದು ಬರುವ ಮಳೆ ಸೀರು ಚರಂಡಿಗಳಲ್ಲ ಸೇರ್ಪಡೆಗೊಳ್ಳುತ್ತಿರುವ ಒಳಚರಂಡಿ ಸೀರನ್ನು ಬಹುತೇಕವಾಲ ತಡೆಯಬಹುದಾಲರುತ್ತದೆ.

ಈ ಮೇಆನ ಕಾಮರಾಲಯನ್ನು ಕೈರೊಂಡು ಅಕವಡಿಸಲಾರುವ ಸಬ್ ಮೇನ್ ಕೊಕವೆ ಮಾರ್ಗಗಣರೆ ಸಿರ್ವಹಣಾ ಪಲಯದ ಪತಿಂಬಂದ ಈರಾರಲೇ ವ್ಯವಸ್ಥಿತವಾಲ ಅಕವಡಿಸಿರುವ 3೦೦ ಮಿಮೀ ವ್ಯಾಸದ RCC ಮತ್ತು 23೦ ಮಿಮೀ ವ್ಯಾಸದ ಒಕಚರಂಡಿ ಕೊಕವೆರಕನ್ನು ಜೋಡಣೆ ಮಾಡಲಾರುವುದು ಎಂದು ತಿಆಸುತ್ತಾ ರೌಡನವಾಕ್ಯ ಕೆರೆಯ ಪಲಸರವನ್ನು ಸಂರಕ್ಷಿಸಬಹುದು ಎಂದು ಸಲ್ಲಸಲಾರುತ್ತಿದೆ."

- 5. Sri Bhat and Sri Kumaraswamy pointed out that, on the North-Eastern side of the lake, sewage is entering the lake and on account of that, the lake has been completely polluted. According to him, BWSSB has to take steps to prevent the sewage entering into the lake.
- 6. Smt Divyashree submitted that, the tender process has already commenced and financial/technical bid has been done. After execution of the tender submitted, the work is

required to be awarded to the contractors. Once the work order is issued in the terms of the tender condition, the contractor will have to execute the work. According to her, completion of the work may take about 6 to 9 months.

7. Photographs produced by Sri Bhat, indicates that, large extent of solid waste is being thrown to the lake. The concerned officials of the BBMP will immediately look into it and take remedial measure to remove the solid waste thrown to the lake and keep the lake clean. It is needless to point out that, the KSPCB has sufficient power under the act to take effective steps to clean the lake.

8. Sri Srikanth, Survey Superintendent is present.

He has submitted that, the survey of the lake has been done and a status report dated: 27-06-2019 along with sketch has been submitted to this office.

It is useful to extract the status report, which reads as hereunder:

Mr

"ವಿಷಯ:- ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು, ಉತ್ತರಹಳ್ಳಿ ಹೋಬಳಿ, ಕದಿರೇನಹಳ್ಳಿ ಗ್ರಾಮದ ಸ.ನಂ: 33 ರ ಕೆರೆಯ ಚಂಟ ಅಳತೆ ಕೆಲಸ ಹೂರೈಸಿ ನಕ್ಷೆ ತಯಾರಿಸಿ ವರದಿ ಸಲ್ಲಿಸುವ ಕುರಿತು. ಉಲ್ಲೇಖ:-ಗೌರವಾನ್ವಿತ ಅಪರ ನಿಭಂದಕರು, ವಿಚಾರಣೆಗಳು-1, ಕರ್ನಾಟಕ ಲೊಕಾಯುಕ್ತ, ಬೆಂಗಳೂರು ರವರ ನೋಟೀಸ್ ಸಂಖ್ಯೆ: ಕಂ.ಲೋಕ್/ಬಿ.ಸಿ.ಡಿ/2518/2018, ದಿ: 25.03.2019.

ವೇಲ್ಕಂಡ ವಿಷಯ ಮತ್ತು ಉಲ್ಲೇಖ ಪತ್ರಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಗೌರವಾಸ್ವಿತ ಕರ್ನಾಟಕ ಲೋಕಾಯುಕ್ತರ ಆದೇಶ ಅನುಸಾರ ತಕ್ಷಣ ಪಾಲನಾ ಕ್ರಮ ಜರುಗಿಸುವ ಸಂಬಂಧ ಪತ್ರದ ನೋಟೀಸ್ನಲ್ಲಿ ವಿಳಾಸಿಸಿರುವವರಿಗೆ ಜಂಟಿ ಅಳತೆ ಬಗ್ಗೆ ಮುಂಚಿತವಾಗಿ ತಿಳುವಳಿಕೆ ನೀಡಿ ಸದರಿಯವರ ಸಮಕ್ಷಮ ಅಳತೆ ಕೆಲಸವನ್ನು ಪೂರೈಸಿ ಕೆರೆ ಜಮೀನಿನ ಒತ್ತುವರಿಗೆ ಸಂಬಂಧಿಸಿದಂತೆ ವರದಿಯನ್ನು ಸಲ್ಲಿಸಲು ಸೂಚಿಸಲಾಗಿರುತ್ತದೆ.

ಉಲ್ಲೇಖ ಪತ್ರದ ಸೂಚನೆಯಂತೆ ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು, ಉತ್ತರಹಳ್ಳಿ ಹೋಬಳಿ, ಕದಿರೇನಹಳ್ಳಿ ಗ್ರಾಮದ ಸ.ನಂ: 33 ರ ಕೆರೆ ಜಮೀನಿನ ಒತ್ತುವರಿಗೆ ಸಂಬಂಧಿಸಿದಂತೆ ತುರ್ತಾಗಿ ಸಂಬಂದಿಸಿ ವೃತ್ತ ಭೂಮಾಪಕರನ್ನು ನಿಯೋಜಿಸಿ ಕೆರೆ ಜಮೀನಿನ ಅಳತೆ ಕೆಲಸವನ್ನು ಪೂರೈಸಿ ನಕ್ಷೆಯೊಂದಿಗೆ ಸ್ಪಷ್ಟವಾದ ವರದಿಯನ್ನು ಸಲ್ಲಿ ಸಲು ಉಲ್ಲೇಖ ಪತ್ರದಂತೆ ಸೂಚಿಸಿದ್ದರ ಮೇರೆಗೆ ನಿಯಮಾನುಸಾರ ಜಂಟಿ ಅಳತ ಕೆಲಸವನ್ನು ಪೂರೈಸಿ ನಕ್ಷೆಯೊಂದಿಗೆ ತುರ್ತಾಗಿ ವರದಿ ಸಲ್ಲಿಸಲು ಸೂಚಿಸಲಾಗಿರುತ್ತದೆ. ಮಾನ್ಯ ಆಯುಕ್ತರು, ಭೂಮಾಪನ ಕಂದಾಯ ವ್ಯವಸ್ಥೆ ಮತ್ತು ಅಧಿಕೃತ ರವರ ಇಲಾಖೆ ಭೂದಾಖಲೆಗಳ SSLR/EST/GC/025/2015-16, Dt: 28.05.2015 ರ ಆದೇಶದಂತೆ ಅಳತೆ ಮಾಡಿ ಗಡಿ ಗುರುತಿಸಿ ತಯಾರಿಸಿದ ಒತ್ತುವರಿ ನಕ್ಷೆಗೆ ತಾಳೆಯಿಟ್ಟು, ಬಿಬಿಎಂಪಿ ಕಾರ್ಯಾಲಯದ ಸಿಬ್ಬಂಧಿಗಳು ಹಾಗೂ ತಹಶೀಲ್ದಾರ್ ಕಾರ್ಯಾಲಯದ ಸಿಬ್ಬಂಧಿಗಳ ಸಮಕ್ಷಮ ಅಳತೆ ಕೆಲಸವನ್ನು ಪೂರೈಸಿ ನಕ್ಸೆಯೊಂದಿಗೆ ಭೂಮಾಪಕರು ವರದಿಯನ್ನು ಸಲ್ಲಿಸಿರುತ್ತಾರೆ. ಸದರಿ ನಕ್ಷೆಯನ್ನು ಲಗತ್ತಿಟ್ಟು ಮಾನ್ಯ ತಮ್ಮ ಅವಗಾಹನೆಗೆ ಸಲ್ಲಿಸಿದೆ."

9. Sketch produced along with the report indicates that, out of 9 acres 23 guntas of land, only 6 acres 23 guntas of land is vacant and 3 acres of land has been encroached upon. It is needless to point out that, the Revenue Department is required to take effective steps for removal of unauthorised encroachment of lake area. Since, there is threat of further encroachment, it is needless to point out

MM

that, the BBMP is required to take immediate steps for fencing the lake.

- For the purpose of taking effective steps for removal of encroachment, I am of the view, it would be in the interest of justice, to issue notice to the Deputy Commissioner, Bengaluru Urban District. Deputy the to notice issue Accordingly, Commissioner, Bengaluru Urban District. The Tahsildar, Bengaluru South who was impleaded as Commissioner, Deputy and No.5 respondent Bengaluru Urban District are directed to take steps for removal of illegal encroachment and file a status report by the next date of hearing.
 - 11. On the last date of hearing the BBMP has filed a status report stating that, they have sent proposal for a sum of rupees Four Crores to develop the lake to the State Government and as soon as the amount sanctioned by the government, steps would be taken to develop the lake in question.

MM

The respondents are given three months time to 12. file the status report with regard to the steps taken by them.

However, the liberty is also reserved to the complainant to give representation to all authorities, pointing out the steps that are required the of one each by taken be to authorities/respondents to rejuvenate/develop the lake. Such representation shall be given, if they so of date the six weeks from within desire communication of this letter.

Communicate this order to all the parties concerned.

List this matter on 06-11-2019 at 3.00 p.m.

Lokayukta, State of Karnataka

 ck^*

ARE-1)