ಕರ್ನಾಟಕ ಲೋಕಾಯುಕ್ತ

ನಂ:ಕಂ.ಲೋಕ್.ಬಿಸಿಡಿ 2519/2018

ಬಹುಮಹಡಿ ಕಟ್ಟಡ, ಬೆಂಗಳೂರು,ದಿನಾಂಕ:10/07/2019

ನೊಟೀಸು

ವಿಷಯ: ಹೆಚ್.ಎಸ್.ದೊರೈಸ್ವಾಮಿ ಎಂಬುವವರು ನಮ್ಮ ಸಂಸ್ಥೆಯಲ್ಲಿ ನೀಡಿರುವ ದೂರಿನ ಕುರಿತು.

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂದಪಟ್ಟಂತೆ ತಮಗೆ ಈ ಮೂಲಕ ಗೌರವಾನ್ವಿತ ಲೋಕಾಯುಕ್ತರವರ ಆದೇಶದಂತೆ ತಮಗೆ ಈ ಮೂಲಕ ತಿಳಿಯ ಪಡಿಸುವುದೆನೆಂದರೆ, ಗೌರವಾನ್ವಿತ ಲೋಕಾಯುಕ್ತರವರು ಹುಲಿಮಾವು ಕೆರೆಗೆ ಸಂಬಂದಪಟ್ಟಂತೆ ದಿನಾಂಕ: 03-07-2018 ರಂದು ಹೊರಡಿಸಿರುವ ಆದೇಶವನ್ನು ಇದರೊಂದಿಗೆ ಲಗತ್ತಿಸಿ ಕಳುಹಿಸಿದ್ದು, ಆದೇಶದಲ್ಲಿ ತಿಳಿಸಿರುವಂತೆ ಪ್ರಸ್ತುತ ವರದಿಯನ್ನು ದಿನಾಂಕ:14.11.2019 ರೊಳಗಾಗಿ ಸಲ್ಲಿಸತಕ್ಕದ್ದು.

ಮುಂದುವರೆದು ಪ್ರಕರಣವನ್ನು ದಿನಾಂಕ:14-11-2019 ಕ್ಕೆ ಮುಂದೂಡಿದೆ.

ಗೌರವಾನ್ವಿತ ಲೋಕಾಯುಕ್ತರವರ ಆದೇಶದನ್ನಯ

ಅಪರ ನಿಭಂದಕರು ವಿಚಾರಣೆಗಳು-1

ಕರ್ನಾಟಕ ಲೋಕಾಯುಕ್ಕಬೆಂಗಳೂರು

To:

- 1) The C.E.O., Namma Bangalore foundation, 2nd floor, No54, Rockline centre, Richmond Road, Bangalore.
- 2) The Commissioner, BBMP, Bangalore
- 3) Sri.Sadiq Ahamed, , Karnataka State Pollution Control Board, Church street Bangalore.
- 4) Sri.Rajashekar, Additional Chief Engineer, (project-1) B W S S B, Cauvery Bhavan, Bangalore
- 5) Sri. Avinash Kumar, Surveyor of Yelahanka Taluk, Bangalore.
- 6) Sri.Manjunath, Suveyor, Bangalore south Taluk, Bangalore

KARNATAKA LOKAYUKTA, BENGALURU

No.Compt/LOK/BCD-2519/2018/ARE-1

Date: 03.07.2019

ORDER

HULIMAVU LAKE -

No one is present on behalf of the complainant and the first respondent — BBMP. However, Sri Sadiq Ahmed, Senior Environmental Officer, Karnataka State Pollution Control Board, (herein after for short as KSPCB) Bengaluru is present on behalf of the second respondent and Sri Rajashekar, Additional Chief Engineer (Project-1), Bengaluru Water Supply & Sewerage Board (herein after for short as BWSSB) is present on behalf of the third respondent. Sri Girish, Surveyor, Bengaluru South Taluk is present

2) Sri Rajashekar, Additional Chief Engineer, BWSSB and Sri Sadiq Ahmed, Senior Environmental Officer of KSPCB submitted that they have already submitted the Status Report. Sri Avinash Kumar, Surveyor of Yelahanka Taluk office submitted that the survey work is required to be carried out by

IN

the Surveyor of Bengaluru South Taluk. He further submitted that the notice issued to him to carry out the survey work has been forwarded to the Surveyor of Bengaluru South Taluk. Sri Girish, Surveyor, Bengaluru South Taluk submitted that one Sri Manjunath, Surveyor is in charge of the said work and since he is held up in Rajakaluve work of fixing the boundaries, he is not able to come today and prays for eight weeks time to survey and submit the report. Accordingly, time sought is granted. Sri Manjnath, Surveyor to survey the lake as directed and submit his report within eight weeks from today. He is given time to survey and submit the report on or before 22.08.2019.

- 3) On such report being submitted by the Surveyor, Bengaluru South Taluk, the Tahsildar, Bengaluru South Taluk is directed to take appropriate steps to evict the encroachments of the lake area if any in accordance with law and submit his report within ten weeks time from the date of the communication of the survey report to him by the Surveyor, Bengaluru South Taluk.
 - The Tahsildar, Bengaluru South Taluk is directed to file graph of the Status Report within ten weeks from the date of the Survey

Report to the Additional Registrar of Enquiries-1, Karnataka Lokayukta, Bengaluru.

All the concerned officers to file the Status Report by the 5) next date of hearing i.e., 14.11.2019. The officers of BBMP is also directed to file the Status Report regarding the steps taken to rejuvenate the lake. On such Status Report being filed, the Additional Registrar of Enquiries-1, Karnataka Lokayukta, Bengaluru to go through the report and submit the Scrutiny Note. The presence of the parties on the next date of hearing is dispensed with. However, if the Tahsildar and the Surveyor of Bengaluru South Taluk fail to carry on the work and submit their report, they are directed to be present on the next date of hearing.

Communicate the copy of this order to the Tahsildar, Bengaluru South Taluk and all the respondents in this ustice P.Vishwanatha Shetty)3/1/019 proceeding.

State of Karnataka